


MetaXpress® 6.5 Software Guide

Peak Analysis

January 2019



Chapter Purpose



The purpose of this chapter is to introduce the user to the new peak analysis feature added in MetaXpress 6.5.

Peak Analysis uses the same peak-finding algorithm as the Peak Pro tool in the SoftMax Pro and ScreenWorks software.

This feature requires purchase of the following part:

5058772 CURVE FITTING APPLICATION MODULE.
Includes Peak Pro Analysis.





Review Plate Data


- 1. Open Review Plata Data
 - In the main toolbar click on




OR

 Under the Screening menu, select Review Plate Data

- 2. Click on the **Select Plate** button
- 3. Browse through the folders to open the plate of interest











Peak Analysis Steps




- 1. Analyze the timelapse plate with an appropriate analysis journal.
 - a) The journal must output an Amplitude measurement (e.g. intensity or % thresholded).
 - b) The journal must output a time measurement (e.g. elapsed time).
 - c) Example journals are available.
- Optionally annotate the plate (Screening > Plate Annotation).
- 3. In the Review Plate Data dialog, go to the **Graph** tab and select the analysis.
- 4. Select Multiple graphs of displayed wells > Time Point
- 5. If viewing graphs, keep the well display montage small (e.g. 2x2 or 3x3), then click **Show Graph**.
- 6. Click Peaks to display the Peak Analysis results for currently displayed wells.



Peak Analysis Steps





- 7. In the Peak Analysis dialog, select the **Time** and **Intensity** measurements.
- Use Open Log and Log Data to export results to Excel or a text file.





Peak attributes

